


1988 KX™500 PARTS DIAGRAM

Shock Absorber(s)



1988 KX™500 PARTS LIST

Shock Absorber(s)

ITEM NAME	PART NUMBER	QUANTITY
CAP (Ref # 11012)	11012-1276	1
GUIDE,SPRING (Ref # 13070)	13070-1161	1
GUIDE,SPRING (Ref # 13070A)	13070-1165	1
PISTON,SHOCKABSORBER (Ref # 13256)	13256-1054	1
CYLINDER-SHOCKABSORBER (Ref # 43089)	43089-1125	1
SHOCKABSORBER (Ref # 45014)	45014-1387	1
ROD,SHOCKABSORBER (Ref # 46102)	46102-1235	1
JOINT-BALL (Ref # 59266)	59266-1071	1
BOLT,DRAIN (Ref # 92002)	92002-1955	1
NUT,SPRING ADJUST (Ref # 92015)	92015-1703	1
NUT,SPRING ADJUST LOCK (Ref # 92015A)	92015-1704	1
RING-SNAP,SHOCKABSORBER (Ref # 92033)	92033-1228	1
RING-SNAP (Ref # 92033A)	92033-1244	1
SEAL-OIL (Ref # 92049)	92049-1306	1
RING-O,ROD (Ref # 92055)	92055-1369	1
RING-O (Ref # 92055A)	92055-1383	1
BUSHING-RUBBER,SHOCKABSORBER (Ref # 92092)	92092-1062	1
SEAL (Ref # 92093)	92093-1253	1
SPRING,SHOCKABSORBER,K=5.2 (Ref # 92144)	92144-1232	1
SPRING,SHOCKABSORBER,K=5.4 (Ref # 92144A)	92144-1310	1
SPRING,SHOCKABSORBER,K=5.6 (Ref # 92144B)	92144-1311	1