


1989 KX™500 PARTS DIAGRAM

Shock Absorber

F2280



1989 KX™500 PARTS LIST

Shock Absorber

ITEM NAME	PART NUMBER	QUANTITY
CAP (Ref # 11012)	11012-1276	1
GUIDE,SPRING (Ref # 13070)	13070-1161	1
GUIDE,SPRING (Ref # 13070A)	13070-1165	1
PISTON,SHOCKABSORBER (Ref # 13256)	13256-1054	1
RESERVOIR,SHOCKABSORBER (Ref # 43078)	43078-1094	1
CYLINDER-SHOCKABSORBER (Ref # 43089)	43089-1132	1
SHOCKABSORBER (Ref # 45014)	45014-1438	1
ROD,SHOCKABSORBER (Ref # 46102)	46102-1270	1
BOLT,DRAIN (Ref # 92002)	92002-1955	1
NUT,SPRING ADJUST (Ref # 92015)	92015-1703	1
NUT,SPRING ADJUST LOCK (Ref # 92015A)	92015-1704	1
RING-SNAP,SHOCKABSORBER (Ref # 92033)	92033-1228	1
SEAL-OIL (Ref # 92049)	92049-1306	1
RING-O,ROD (Ref # 92055)	92055-1369	1
RING-O (Ref # 92055A)	92055-1383	1
SPRING,SHOCKABSORBER,K=5.2 (Ref # 92144)	92144-1394	1
SPRING,SHOCKABSORBER,K=5.4 (Ref # 92144A)	92144-1396	1
SPRING,SHOCKABSORBER,K=5.6 (Ref # 92144B)	92144-1398	1