


1991 NINJA® ZX™-7 PARTS DIAGRAM

Starter Motor



1991 NINJA® ZX™-7 PARTS LIST

Starter Motor

ITEM NAME	PART NUMBER	QUANTITY
SHAFT (Ref # 13107)	13107-1112	1
HOLDER-ASSY,CARBON BRUSH (Ref # 14079)	14079-1082	1
GEAR,IDLE (Ref # 16085)	16085-1104	1
SPRING-BRUSH (Ref # 21040)	21040-1051	1
STARTER-ELECTRIC (Ref # 21163)	21163-1193	1
TERMINAL,STARTER (Ref # 21169)	21169-1058	1
FUSE,30A-G (Ref # 26006)	26006-1006	1
WIRE-LEAD,STARTER MOTOR (Ref # 26011)	26011-1473	1
SWITCH,MAGNETIC (Ref # 27010)	27010-1213	1
BOLT,6X20 (Ref # 92001)	92001-1947	1
NUT (Ref # 92015)	92015-1623	1
WASHER (Ref # 92022)	92022-2200	1
RING-O,62MM (Ref # 92055)	92055-1260	1
RING-O,4.5MM (Ref # 92055A)	92055-1261	1
RING-O,24.4MM (Ref # 92055B)	92055-1262	1
GROMMET,STARTER TERMINAL (Ref # 92071)	92071-1120	1
GROMMET,TERMINAL (Ref # 92071A)	92071-1121	1
DAMPER,MAGNETIC SWITCH (Ref # 92075)	92075-1863	1
BOLT (Ref # 92150)	92150-1237	1
NUT-HEX,6MM (Ref # 311)	311B0600	1
WASHER-SPRING,6MM (Ref # 461)	461F0600	1