


# 1991 Jet Mate PARTS DIAGRAM

Cooling



## 1991 Jet Mate PARTS LIST

### Cooling

ITEM NAME	PART NUMBER	QUANTITY
HOLDER-ASSY (Ref # 14079)	14079-3705	1
WARNER (Ref # 25025)	25025-3702	1
SWITCH,WATER SENSOR (Ref # 27010)	27010-3719	1
JOINT (Ref # 59071)	59071-3717	1
BOLT,6X12 (Ref # 92002)	92002-3763	1
NUT (Ref # 92015)	92015-3798	1
CLAMP (Ref # 92037)	92037-1173	3
TUBE,5.8X10.8X360 (Ref # 92059)	92059-3743	1
GROMMET (Ref # 92071)	92071-3769	1
CLAMP (Ref # 92170)	92170-3720	4
TUBE (Ref # 92190)	92190-3701	1
TUBE (Ref # 92190A)	92190-3703	1
TUBE,5.8X10.8X730 (Ref # 92190B)	92190-3706	1
SCREW-PAN-CROS,5X25 (Ref # 220)	220R0525	1
WASHER-PLAIN,5MM (Ref # 411)	411S0500	2