


1990 TS PARTS DIAGRAM

Cables

F3175



1990 TS PARTS LIST

Cables

ITEM NAME	PART NUMBER	QUANTITY
BRACKET,STARTER CABLE (Ref # 11046A)	11046-3786	1
BRACKET,STEERING CABLE (Ref # 11046B)	11046-3843	1
PLATE (Ref # 13183A)	13183-3754	1
PLATE,THROTTLE CABLE (Ref # 13183B)	13183-3758	1
DETENT (Ref # 32085)	59346-504	1
CABLE-THROTTLE (Ref # 54012)	54012-3719	1
CABLE-STARTER (Ref # 54017)	54017-3712	1
REEL (Ref # 59101)	59101-3706	1
CABLE-STRG (Ref # 59406)	59406-3714	1
SCREW,4X8 (Ref # 92009)	92009-3729	1
SCREW,5X12 (Ref # 92009A)	92009-3740	1
NUT,18MM (Ref # 92015)	92015-3778	1
NUT,20MM (Ref # 92015A)	92015-526	1
WASHER (Ref # 92022)	92022-535	1
RING-SNAP,7MM (Ref # 92033)	92033-3704	1
RING-SNAP (Ref # 92033A)	92036-501	1
GROMMET (Ref # 92071)	92071-3760	1
GROMMET (Ref # 92071B)	92071-3766	1
GROMMET (Ref # 92071C)	92071-3767	1
GROMMET (Ref # 92071D)	92071-3771	1
BAND,L=123 (Ref # 92072)	92072-030	1
BAND,L=186 (Ref # 92072A)	92072-056	1
KNOB (Ref # 92077)	92077-3709	1
BALL,3MM (Ref # 92140)	92140-3702	1
SPRING (Ref # 92144)	92144-3712	1
CLAMP (Ref # 92170)	92170-3705	1
CLAMP (Ref # 92170C)	92170-3723	1
CLAMP (Ref # 92170D)	92170-3724	1
TUBE,22X24X250 (Ref # 92190)	92190-3710	1

1990 TS PARTS LIST

Cables

ITEM NAME	PART NUMBER	QUANTITY
WASHER,8X14.5X1 (Ref # 92200A)	92200-3704	1
BOLT-WP,6X12 (Ref # 156)	156R0612	1
SCREW-PAN-CROS,4X6 (Ref # 220)	220R0406	1
SCREW-PAN-WS-CROS,6X14 (Ref # 223)	223R0614	1
NUT-HEX,6MM (Ref # 311)	311R0600	1
W-PLAIN-S,10MM (Ref # 410)	410S1000	1
WASHER-SPRING,6MM (Ref # 461)	461S0600	1
O RING,8MM (Ref # 670)	670B1508	1
O RING,11MM (Ref # 670A)	670B2011	1