


1999 1100 ZXi

PARTS DIAGRAM

Carburetor Parts(JH1100-A3/A4)

E1612B



1999 1100 ZXi

PARTS LIST

Carburetor Parts(JH1100-A3/A4)

ITEM NAME	PART NUMBER	QUANTITY
GASKET,DIAPHRAGM COVER (Ref # 11060)	11060-3789	3
GUIDE,VACUUM VALVE (Ref # 13070)	13070-3726	3
COVER-COMP,MIXING (Ref # 14041)	14041-1100	3
COVER,DIAPHRAGM (Ref # 14090)	14090-3816	3
JET-NEEDLE,N6PA (Ref # 16017)	16017-3702	3
VALVE-FLOAT (Ref # 16030)	16030-3704	3
ARM-FLOAT (Ref # 16055)	16055-3702	3
VALVE-CHECK (Ref # 16087)	16087-3706	3
VALVE,VACUUM (Ref # 16126)	16126-3705	3
JET-SLOW,#32 (Ref # 16158)	16158-3723	3
JET-SLOW,#35 (Ref # 16158A)	16158-3726	3
CASE,JET (Ref # 32099)	32099-3833	3
DIAPHRAGM,CARBURETOR (Ref # 43028)	43028-3711	3
DIAPHRAGM (Ref # 43028A)	43028-3718	1
PACKING,JET CASE (Ref # 43049)	43049-3713	3
CASE-PUMP (Ref # 59336)	59336-3715	1
SCREW (Ref # 92009)	92009-1771	3
SCREW,3X8 (Ref # 92009A)	92009-3712	3
SCREW,4X8 (Ref # 92009B)	92009-3804	6
SCREW,VALVE GUIDE (Ref # 92009C)	92009-3839	6
SCREW,DIAPHRAGM COVER (Ref # 92009D)	92009-3840	12
SCREW,MIXING COVER (Ref # 92009E)	92009-3841	12
RING-O,VACUUM VALVE GUIDE (Ref # 92055)	92055-3749	3
JET-MAIN,#165 (Ref # 92063)	92063-3720	3
JET-MAIN,#160 (Ref # 92063A)	92063-3722	3
SPRING,VACUUM VALVE (Ref # 92144)	92144-1962	3
SPRING,FLOAT ARM (Ref # 92144A)	92144-3764	3
SPRING,JET NEEDLE (Ref # 92145)	92145-3707	3
COLLAR,JET NEEDLE (Ref # 92152)	92152-3706	3