


2002 Ultra 130

PARTS DIAGRAM

Ignition System(JH1100-B2)



2002 Ultra 130

PARTS LIST

Ignition System(JH1100-B2)

ITEM NAME	PART NUMBER	QUANTITY
BOLT,6X20 (Ref # 110)	110R0620	2
NUT-HEX,6MM (Ref # 311)	311R0600	2
WASHER-PLAIN-SMALL,6MM (Ref # 410)	410S0600	2
CAP,HOLDER (Ref # 11012)	11012-3768	3
CAP (Ref # 11012A)	11012-3791	1
BRACKET,COIL (Ref # 11052)	11052-3754	1
BRACKET,FUSE (Ref # 11053)	11053-3726	1
PLATE (Ref # 13271)	13271-3820	1
PLATE (Ref # 13271A)	13271-3821	1
COIL-IGNITION,#1 BLACK (Ref # 21121)	21121-3719	1
COIL-IGNITION,#2 GREEN (Ref # 21121A)	21121-3720	1
COIL-IGNITION,#3 WHITE (Ref # 21121B)	21121-3721	1
FUSE-ASSY (Ref # 26004)	26004-3725	1
FUSE,10A-R (Ref # 26006)	26006-1007	2
FUSE,20A-Y (Ref # 26006A)	26006-1051	4
SWITCH (Ref # 27010)	27010-3774	1
BOLT,6X35 (Ref # 92002)	92002-3715	6
SCREW,6X15 (Ref # 92009)	92009-3830	6
WASHER (Ref # 92022)	92022-567	2
COLLAR,6.2X10X10 (Ref # 92027)	92027-3705	6
CLAMP,HOSE (Ref # 92037)	92037-1603	3
RING-O (Ref # 92055)	92055-1292	1
PLUG-SPARK,PZFR7G-G(NGK),SOLID (Ref # 92070)	92070-3705	3
BAND,L=201 (Ref # 92072)	92072-3778	1
BOLT,6X12 (Ref # 92151)	92151-3724	2