


1982 KZ1300-A4

PARTS DIAGRAM

TURN SIGNALS

F2730-0081



1982 KZ1300-A4

PARTS LIST TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
GASKET,TURN SIGNAL (Ref # 11009)	11009-1102	4
LAMP ASSY,TURN SIGNAL (Ref # 23040)	23040-1021	2
LAMP,ASSY,TURN SIGNAL (Ref # 23040A)	23040-1022	2
LENS SIGNAL LAMP FR (Ref # 23048)	23048-1020	4
BRACKET,TURN SIGNAL (Ref # 23051)	23051-1023	4
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	4
COLLAR (Ref # 92027)	92027-147	4
BULB 12V 32CP (Ref # 92069)	92069-055	2
BULB,12V 23/8W (Ref # 92069A)	92069-060	2
WASHER-PLAIN,4MM (Ref # 92075)	23058-002	8
DAMPER RUBBER (Ref # 92075A)	92075-128	4
DAMPER RUBBER,SIG LM (Ref # 92075B)	92075-158	4
BOLT-UPSET (Ref # 110)	112G0630	4
SCREW,PAN HEAD,4X16 (Ref # 220)	220E0416A	8
NUT 6MM (Ref # 311)	311B0600	4
WASHER PLAIN 6MM (Ref # 411)	411B0600	8
WASHER SPRING 6MM (Ref # 461)	461F0600	4