


1984 KX60 PARTS DIAGRAM

SWING ARM

F2140-0139



1984 KX60 PARTS LIST

SWING ARM

ITEM NAME	PART NUMBER	QUANTITY
CAP,SWING ARM (Ref # 11012)	11012-1263	4
GUIDE-CHAIN,FR (Ref # 12053)	12053-1069	1
ARM-COMP-SWING (Ref # 33001)	33001-1147	1
SHAFT-SWING ARM,PIVOT (Ref # 33032)	33032-1031	1
ADJUSTER,CHAIN (Ref # 33040)	33040-1009	2
SLEEVE,SWING ARM,L=34 (Ref # 42036)	42036-1067	2
GUARD,CHAIN,RR (Ref # 55020)	55020-1081	1
BOLT,6X38 (Ref # 92001)	92001-1463	2
SCREW,6X10 (Ref # 92009)	92009-1286	2
NUT (Ref # 92015)	92015-1774	1
NUT,LOCK 6MM (Ref # 92015A)	92017-014	1
COLLAR,RADIATOR GUARD (Ref # 92027)	92027-1183	2
COLLAR,CHAIN GUIDE (Ref # 92027A)	92027-1495	1
BEARING-NEEDLE (Ref # 92046)	92046-1046	2
ROLLER,CHAIN GUIDE (Ref # 92122)	92122-1030	1
BOLT-FLANGED,6X45 (Ref # 130)	130B0645	2
BOLT-FLANGED,6X50 (Ref # 130A)	130B0650	1
NUT 6MM (Ref # 311)	311B0600	2
WASHER PLAIN 6MM (Ref # 411)	411B0600	1