


1999 Ultra 150

PARTS DIAGRAM

Cables

F3175



1999 Ultra 150

PARTS LIST

Cables

ITEM NAME	PART NUMBER	QUANTITY
WASHER-PLAIN,8MM (Ref # 411)	411S0800	1
O RING,11MM (Ref # 670A)	670B2011	1
BRACKET (Ref # 11050)	11050-3767	1
BRACKET (Ref # 11051)	11051-3701	1
BRACKET,STARTER CABLE (Ref # 11051A)	11051-3744	1
HOLDER (Ref # 13091)	13091-3712	2
PLATE (Ref # 13183)	13183-3809	1
HOLDER-CABLE (Ref # 14044)	14044-3736	1
CABLE-THROTTLE (Ref # 54012)	54012-3764	1
REEL (Ref # 59101)	59101-3714	1
CABLE-CHOKE (Ref # 59401)	59401-3724	1
CABLE-STRG (Ref # 59406)	59406-3771	1
BOLT,6X30 (Ref # 92002)	92002-3726	1
SCREW,5X16 (Ref # 92009)	92009-3789	2
SCREW,4X12 (Ref # 92009A)	92009-3838	1
NUT,20MM (Ref # 92015)	92015-526	1
WASHER,6.5X20X1.5 (Ref # 92022)	92022-3710	1
WASHER (Ref # 92022A)	92022-535	1
BUSHING (Ref # 92028)	92028-3769	1
RING-SNAP (Ref # 92036)	92036-501	1
PIN (Ref # 92043)	92043-3752	1
PLUG,FUEL&CHOKE KNOB,R.BLACK (Ref # 92066)	92066-3755-6S	1
KNOB,FUEL&CHOKE,R.BLACK (Ref # 92077)	92077-3730-6S	1
COLLAR,6.2X10X19 (Ref # 92143)	92143-3733	1
SPRING (Ref # 92145)	92145-3712	1
BOLT,6X20 (Ref # 92150)	92150-3758	3
BOLT,5X16 (Ref # 92150A)	92150-3778	1
WASHER,8.5X34X0.5 (Ref # 92200)	92200-3770	1
NUT (Ref # 92210)	92210-3746	1