


1983 GPz 750

PARTS DIAGRAM TRANSMISSION

Kawasaki
Let the Good Times Roll®

E1361-0117



1983 GPz 750

PARTS LIST TRANSMISSION

ITEM NAME	PART NUMBER	QUANTITY
SHAFT,DRIVE (Ref # 13127)	13127-1018	1
SHAFT-TRANSMISSION OU (Ref # 13128)	13128-1051	1
LOW GEAR,OUTPUT SHAFT (Ref # 13129)	13129-1046	1
2ND GEAR,OUTPUT SHAFT (Ref # 13129A)	13129-1047	1
3RD GEAR,OUTPUT SHAFT (Ref # 13129B)	13129-1048	1
4TH GEAR,OUTPUT SHAFT (Ref # 13129C)	13129-1049	1
TOP GEAR,DRIVEN SHAFT (Ref # 13129D)	13129-1201	1
GEAR,INPUT TOP,24T (Ref # 13129E)	13129-1425	1
GEAR,INPUT 3RD&22T (Ref # 13129F)	13260-1202	1
GEAR,INPUT 4TH,25T (Ref # 13129G)	13129-1446	1
2ND GEAR,DRIVE (Ref # 13129H)	13130-041	1
SPROCKET-OUTPUT,15T (Ref # 13144)	13144-1084	1
NUT,20MM (Ref # 92015)	92015-1254	1
WASHER,PLAIN (Ref # 92022)	92022-1026	AR
WASHER (Ref # 92022A)	92200-1065	1
WASHER THRUST (Ref # 92022B)	92022-112	2
SHIM-KICK SHAFT (Ref # 92022C)	92022-144	AR
WASHER PLAIN (Ref # 92022D)	92022-161	2
WASHER,LOCK (Ref # 92022E)	92024-069	3
COLLAR,25X32X23.5L (Ref # 92027)	92027-1106	1
BUSHING,DRV SHFT TOP (Ref # 92028)	92028-1007	1
BUSHING,27X34X18.6 (Ref # 92028A)	92028-1151	1
BUSHING,INPUT SHAFT (Ref # 92028B)	92028-1199	1
CIRCLIP (Ref # 92033)	92033-015	2
CIRCLIP (Ref # 92033A)	92033-026	2
BEARING,BALL (Ref # 92045)	92045-035	2
BEARING-NEEDLE,20V271 (Ref # 92046)	92046-1045	2
CIRCLIP,30MM (Ref # 480)	480J3000	3
BALL STEEL 5/32' (Ref # 600)	600A0500	3