


1984 KD80

PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS

F2140-0188



1984 KD80

PARTS LIST

SWING ARM/SHOCK ABSORBERS

ITEM NAME	PART NUMBER	QUANTITY
ARM,SWINGING (Ref # 33001)	33001-1045	1
SHAFT,SWING ARM PIVOT (Ref # 33032)	33032-043	1
ADJUSTER CHAIN (Ref # 33040)	33040-008	2
SHOCKABSORBER (Ref # 45014A)	45014-1214	2
GUARD,CHAIN (Ref # 55020)	55020-012	1
NUT,12MM (Ref # 92015A)	92015-1381	1
NUT,6MM (Ref # 92015B)	92015-1391	4
NUT,12MM (Ref # 92015C)	92015-1426	2
WASHER,12MM (Ref # 92022A)	92022-1538	2
WASHER SPRING 12MM (Ref # 92022B)	461F1200	1
WASHER,6.5X16X2 (Ref # 92022C)	92022-1565	2
BUSH SWING ARM SHAFT (Ref # 92092)	92092-005	2
BOLT-FINE-WS (Ref # 160A)	160N1030	2
BOLT-UPSET-WSP (Canada) (Ref # 187)	187X0616	2
WASHER PLAIN 12MM (Ref # 410)	410B1200	2