


1986 X2

PARTS DIAGRAM

DRIVE SHAFT

E3134-0004



1986 X2

PARTS LIST DRIVE SHAFT

ITEM NAME	PART NUMBER	QUANTITY
HOLDER (Ref # 13091)	13091-3730	1
COVER (Ref # 14024)	14024-3728	1
SHAFT-DRIVE (Ref # 39159)	39159-3711	1
COUPLING (Ref # 42034)	42034-3705	1
WASHER (Ref # 92022)	92022-3728	1
WASHER (Ref # 92022A)	92022-1964	4
RING-SNAP (Ref # 92033)	92033-3713	1
CLAMP,L=100 (Ref # 92037)	92037-3736	1
CLAMP,L=100 (Ref # 92037A)	92037-3736	1
BEARING-BALL (Ref # 92045)	92045-3705	1
SEAL-OIL,S620426 (Ref # 92049)	92049-3707	2
SEAL,OIL SCY20368 (Ref # 92049A)	92050-502	1
SEAL,OIL SC20367 (Ref # 92049B)	92050-503	1
TUBE,VINYL,5X73 (Ref # 92059)	92059-3017	1
DAMPER RUBBER,COUPLNG (Ref # 92075)	92075-520	1
BOLT-WS-SMALL (Ref # 153)	153R0825	4
NUT,6M/M (Ref # 311)	311R0600	2