

1981 KDX80

PARTS LIST

CABLES/NUMBER PLATE

| ITEM NAME | PART NUMBER | QUANTITY |
|---------------------------------|---------------|----------|
| SCREW PAN HEAD 5X10 (Ref # 1) | 220B0510 | |
| WASHER SPRING 5MM (Ref # 2) | 461F0500 | |
| BOLT-UPSET,6X12 (Ref # 3) | 112G0612 | |
| WASHER PLAIN 6MM (Ref # 4) | 411B0600 | |
| WASHER SPRING 6MM (Ref # 5) | 461F0600 | |
| CLAMP,CABLE (Ref # 6) | 92037-092 | |
| BOLT-UPSET (Ref # 7) | 112G0618 | |
| NUT 6MM (Ref # 8) | 311B0600 | |
| WASHER SPRING 6MM (Ref # 9) | 461F0600 | |
| CLAMP,CABLE (Ref # 10) | 92037-092 | |
| CABLE,BRAKE,FRONT (Ref # 11) | 54005-1013 | |
| CABLE,CLUTCH (Ref # 12) | 54011-1035 | |
| CABLE,THROTTLE (Ref # 13) | 54012-1022 | |
| BAND,WIRING HARNESS (Ref # 14) | 92072-056 | |
| PLATE,NUMBER,L.GREEN (Ref # 15) | 58029-1002-6W | |
| "O" RING,135MM (Ref # 16) | 92055-1058 | |