


# 1970 G3SS PARTS DIAGRAM

METER/HEADLIGHT ('69-'73)



Ref.No. 1

- 1
- 2
- 3
- 4, 28, 31~34
- 6~18
- 6~20
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32
- 33
- 34
- 35
- 36
- 37
- 38
- 39
- 40

# 1970 G3SS PARTS LIST

METER/HEADLIGHT ('69-'73)

| ITEM NAME                           | PART NUMBER  | QUANTITY |
|-------------------------------------|--------------|----------|
| SPEEDOMETER ASSY MPH (Ref # 1)      | 25001-008    | 1        |
| SPEEDOMETER ASSY,MPH (Ref # 1)      | 25001-050    | 1        |
| BULB 6V 1.5W (Ref # 2)              | 92069-024    | 3        |
| SOCKET SPEEDOMETER (Ref # 3)        | 25011-008    | 1        |
| SPEEDOMETER ASSY,MPH (Ref # 4,28,3) | 25001-050    | 1        |
| LAMP UNIT HEAD (Ref # 6~18)         | 23004-011    | 1        |
| LAMP UNIT HEAD (Ref # 6~20)         | 23003-009    | 1        |
| UNAVAILABLE IN PRICE BOOK (Ref # 5) | 23005-021    | 1        |
| CASE-HEAD LAMP,BLACK (Ref # 5)      | 23005-021-21 | 1        |
| RIM HEAD LAMP (Ref # 6)             | 23006-020    | 1        |
| LENS UNIT HEAD LAMP (Ref # 7)       | 23007-017    | 1        |
| SEALED BEAM UNIT (Ref # 8)          | 23007-023    | 1        |
| BULB 6V 25/25W (Ref # 9)            | 92069-031    | 1        |
| SOCKET HEAD LAMP (Ref # 10)         | 23008-009    | 1        |
| SOCKET ASSY,HD LIGHT (Ref # 11)     | 23008-044    | 1        |
| SPRING LENS FITTING (Ref # 12)      | 23014-008    | 1        |
| SCREW ADJUST (Ref # 13)             | 23019-013    | 1        |
| WASHER ADJUST (Ref # 14)            | 23021-007    | 1        |
| NUT ADJUST (Ref # 15)               | 23020-012    | 1        |
| SCREW FITTING (Ref # 16)            | 23019-014    | 2        |
| NUT ADJUST (Ref # 17)               | 23020-013    | 6        |
| WASHER FITTING (Ref # 18)           | 23058-001    | 1        |
| NUT,4MM (Ref # 19)                  | 311B0400     | 2        |
| WASHER SPRING 4MM (Ref # 20)        | 461F0400     | 2        |
| SCREW OVL CNTSNK 5X8 (Ref # 21)     | 222E0508A    | 1        |
| GROMMET WIRING HARNES (Ref # 22)    | 23023-007    | 2        |
| NUT 10MM (Ref # 23)                 | 92016-027    | 2        |
| BOLT HEX HEAD 10X20 (Ref # 24)      | 113N1020     | 2        |
| WASHER PLAIN 10MM (Ref # 25)        | 411B1000     | 2        |

## 1970 G3SS PARTS LIST

METER/HEADLIGHT ('69-'73)

| ITEM NAME                        | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| WASHER SPRING 10MM (Ref # 26)    | 461F1000    | 2        |
| WASHER LOCK 10MM (Ref # 27)      | 463H1000    | 2        |
| COVER-SPEEDOMETER (Ref # 28)     | 25012-003   | 1        |
| BULB-6V 3W (Ref # 29)            | 92069-053   | 1        |
| SOCKET-SPEEDOMETER (Ref # 30)    | 25011-025   | 1        |
| BRACKET-SPEEDOMETER (Ref # 31)   | 25008-021   | 1        |
| WASHER PLAIN 5MM (Ref # 32)      | 410B0500    | 2        |
| WASHER SPRING 5MM (Ref # 33)     | 461F0500    | 2        |
| NUT,5MM (Ref # 34)               | 311B0500    | 2        |
| DAMPER RUBB SPEEDMETR (Ref # 35) | 92075-024   | 2        |
| WASHER SPRING 6MM (Ref # 36)     | 461F0600    | 3        |
| HORN (Ref # 37)                  | 27003-009   | 1        |
| HORN (Ref # 38)                  | 27003-055   | 1        |
| HORN (Ref # 38)                  | 27003-055   | 1        |
| NUT 6MM (Ref # 39)               | 311B0600    | 3        |
| LEAD WIRE,HORN (Ref # 40)        | 26002-023   | 1        |