


1992 550 SX PARTS DIAGRAM

Starter Motor

E1840



1992 550 SX PARTS LIST

Starter Motor

ITEM NAME	PART NUMBER	QUANTITY
GEAR-COMP,SPUR (Ref # 13216)	13216-3703	1
HOLDER-ASSY,BRUSH (Ref # 14079)	14079-3706	1
BRUSH,CARBON(+) (Ref # 21039)	21039-3704	1
SPRING-BRUSH (Ref # 21040)	21040-3701	2
STARTER-ELECTRIC (Ref # 21163)	21163-3710	1
STOPPER,GEAR (Ref # 32085)	32085-3718	1
BOLT,6X20 (Ref # 92002)	92002-3755	1
SCREW,4X10 (Ref # 92009)	92009-3785	2
NUT,STARTER TERMINAL (Ref # 92015)	92015-3820	1
SHIM,STARTER,T=0.4 (Ref # 92025)	92025-3012	AR
SHIM,STARTER,T=0.6 (Ref # 92025A)	92025-3013	AR
SHIM,STARTER,T=0.8 (Ref # 92025B)	92025-3014	AR
SPACER,TERMINAL,OUT (Ref # 92026)	92026-3704	1
SPACER,TERMINAL,IN (Ref # 92026A)	92026-3705	1
RING-SNAP (Ref # 92036)	92036-517	1
RING-O,STARTER TERMINAL (Ref # 92055)	92055-3728	1
RING-O,BOLT (Ref # 92055A)	92055-3729	2
RING-O,YOKE (Ref # 92055B)	92055-3730	2
RING-O (Ref # 92055C)	92055-516	1
BOLT,8X75 (Ref # 92150)	92150-3756	2
BOLT,5X120 (Ref # 92150A)	92150-3783	2
WASHER,THRUST (Ref # 92200)	92200-3734	1
WASHER-PLAIN-SMALL,8MM (Ref # 410)	410S0800	2