


1978 KZ200-A1

PARTS DIAGRAM

CABLES



1978 KZ200-A1

PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 1)	54001-058	1
CABLE,FRONT BRAKE (Ref # 2)	54005-089	1
CABLE,CLUTCH (Ref # 3)	54011-090	1
CABLE,THROTTLE (Ref # 4)	54012-144	1
CABLE,TACHOMETER (Ref # 5)	54018-024	1
CLAMP,CABLE (Ref # 6)	92037-093	1
CLAMP,CABLE (Ref # 7)	92037-205	1
CLAMP,CABLE (Ref # 8)	92037-206	1
BOLT-UPSET,6X12 (Ref # 9)	112G0612	2
WASHER SPRING 6MM (Ref # 10)	461F0600	2
WASHER PLAIN 6MM (Ref # 11)	411B0600	2
CLAMP,CABLE (Ref # 12)	92037-092	2