


1978 KZ400-A2

PARTS DIAGRAM

CARBURETOR ASSY (KZ400-A2)



1978 KZ400-A2

PARTS LIST

CARBURETOR ASSY (KZ400-A2)

| ITEM NAME | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| CARBURETOR ASSY (Ref # 1) | 16001-300 | |
| CARBURETOR,L.H. (Ref # 2) | 16001-1006 | |
| CARBURETOR,R.H. (Ref # 3) | 16001-1007 | |
| PLATE,STAY (Ref # 4) | 16065-1001 | |
| SCREW,6X16 (Ref # 5) | 92009-1129 | |
| BRACKET,THR.CBL (Ref # 6) | 11034-1008 | |
| SPRING (Ref # 7) | 92081-1003 | |
| ROCKER ARM (Ref # 8) | 11034-1009 | |
| WASHER,PLAIN (Ref # 9) | 16039-027 | |
| WASHER SPRING 5MM (Ref # 10) | 461F0500 | |
| SCREW-PAN-CROS,5X25 (Ref # 11) | 220B0525 | |
| COLLAR,CHOKE LEVER (Ref # 12) | 16073-1001 | |
| SPRING (Ref # 13) | 92081-1004 | |
| BALL,STEEL,1/8" (Ref # 14) | 600A0400 | |
| CAM,CHOKE LINK (Ref # 15) | 13169-1007 | |
| BRACKET,CHOKE LEVER (Ref # 16) | 11034-1010 | |
| NUT,5MM (Ref # 17) | 311B0500 | |
| SCREW-PAN-HEAD 3X6 (Ref # 18) | 220B0306 | |
| BOLT,HEX HEAD,6X22 (Ref # 19) | 92009-1006 | |
| SCREW,SLOTTED (Ref # 20) | 16021-1002 | |
| SPRING (Ref # 21) | 92081-1006 | |
| SPRING,THR.STOP SCREW (Ref # 22) | 92081-1005 | |
| WASHER PLAIN 5MM (Ref # 23) | 410B0500 | |
| SCREW,THROTTLE STOP (Ref # 24) | 16021-1001 | |
| HOSE,FUEL INLET (Ref # 25) | 92059-1001 | |
| CLAMP,FUEL HOSE (Ref # 26) | 92037-1040 | |
| NIPPLE,FUEL HOSE (Ref # 27) | 16046-013 | |
| "O" RING (Ref # 28) | 92055-1004 | |
| HOSE,FUEL OVERFLOW (Ref # 29) | 92059-111 | |

1978 KZ400-A2

PARTS LIST

CARBURETOR ASSY (KZ400-A2)

| ITEM NAME | PART NUMBER | QUANTITY |
|--------------------------------|-------------|----------|
| CLAMP,TUBE,OVERFLOW (Ref # 30) | 92037-1142 | |
| HOSE (Ref # 31) | 92059-110 | |
| CLAMP,OVERFLOW HOSE (Ref # 32) | 16044-002 | |
| WASHER SPRING 3MM (Ref # 33) | 461F0300 | |