


1981 KZ440-B2

PARTS DIAGRAM

TURN SIGNALS ('81 B2)

F2730-0008



1981 KZ440-B2

PARTS LIST

TURN SIGNALS ('81 B2)

ITEM NAME	PART NUMBER	QUANTITY
GASKET,TURN SIG LAMP (Ref # 11009)	23050-002	4
LAMP-TURN SIGNAL (Ref # 23040)	23040-029	2
LIGHT ASSY,TRN SG,R.H (Ref # 23040A)	23040-1005	1
LIGHT ASSY,TRN,SG,L.H (Ref # 23040B)	23040-1006	1
LENS-SIGNAL LAMP (Ref # 23048)	23048-1024	4
BRACKET,TURN SIGNAL.L (Ref # 23051)	23051-053	4
COLLAR,SIGNAL LAMP (Ref # 92027)	92027-1060	2
COLLAR (Ref # 92027A)	92027-147	2
BULB 12V 32CP (Ref # 92069)	92069-055	2
BULB,12V 23/8W (Ref # 92069A)	92069-060	2
WASHER-PLAIN,4MM (Ref # 92075)	23058-002	8
DAMPER RUBBER (Ref # 92075A)	92075-128	4
DAMPER RUBBER,SIG LM (Ref # 92075B)	92075-158	4
BOLT-UPSET (Ref # 110)	112G0630	4
SCREW-PAN HEAD,4X35 (Ref # 220)	220E0435A	8
NUT 6MM (Ref # 311)	311B0600	4
NUT 10MM (Ref # 315)	315B1000	4
WASHER PLAIN 6MM (Ref # 411)	411B0600	8
WASHER SPRING 6MM (Ref # 461)	461F0600	4
WASHER SPRING 10MM (Ref # 461A)	461F1000	4