


1980 LTD II

PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS



1980 LTD II

PARTS LIST

SWING ARM/SHOCK ABSORBERS

ITEM NAME	PART NUMBER	QUANTITY
SWING ARM (Ref # 1)	33001-1040	1
CAP,SWING ARM (Ref # 2)	33035-009	2
SLEEVE,SWING ARM (Ref # 3)	42036-1014	1
GREASE NIPPLE (Ref # 4)	92005-002	1
BEARING-NEEDLE,HK221 (Ref # 5)	92046-1115	4
SHAFT,SWING ARM PIVO (Ref # 6)	33032-047	1
NUT-SELF LOCKING (Ref # 7)	92019-012	1
NUT 10MM (Ref # 8)	315B1000	2
ADJUSTER,CHAIN (Ref # 9)	33040-066	2
BOLT-CHN ADJUST 10MM (Ref # 10)	92001-143	2
BOLT HEX HEAD 10X35 (Ref # 11)	113N1035	2
WASHER SPRING 10MM (Ref # 12)	461F1000	2
WASHER PLAIN 10MM (Ref # 13)	411B1000	2
WASHER SPRING 10MM (Ref # 14)	461F1000	2
NUT SHOCK ABSORBER (Ref # 15)	92020-003	2
WASHER,PLAIN (Ref # 16)	92022-1022	1
SHOCK ABSBR RR (Ref # 17)	45014-1042	2
BUSHING,SHCK ABS RUB (Ref # 18)	45017-015	2
BUSHING, SHCK ABS RU (Ref # 19)	45017-012	2
BUSHING,SHOCK ABSORB (Ref # 20)	45016-008	2