


1980 KZ1300-A2 PARTS DIAGRAM

CABLES



1980 KZ1300-A2 PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
GUIDE,TACHOMETER CABL (Ref # 1)	13070-1012	1
GUIDE,CLUTCH CABLE (Ref # 2)	13070-1013	1
GUIDE,SPEEDOMETER (Ref # 3)	13070-1015	1
GUIDE,CLUTCH CABLE (Ref # 4)	13070-1016	1
GUIDE,THROTTLE CABLE (Ref # 5)	13070-1017	1
BOLT-UPSET,6X12 (Ref # 6)	112G0612	2
WASHER SPRING 6MM (Ref # 7)	461F0600	2
WASHER PLAIN 6MM (Ref # 10)	411B0600	1
CABLE,SPEEDOMETER (Ref # 11)	54001-1013	1
CABLE-CLUTCH (Ref # 12)	54011-1139	1
CABLE,THROTTLE (Ref # 13)	54012-1027	1
CABLE,THROTTLE (Ref # 14)	54012-1028	1
CABLE,TACHOMETER (Ref # 15)	54018-1005	1
CLAMP,CABLE (Ref # 16)	92037-093	1