


# 1982 CSR

## PARTS DIAGRAM

### CABLES

F2540-0050



# 1982 CSR

## PARTS LIST

### CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 54001)	54001-1029	1
CABLE-CLUTCH (Ref # 54011)	54011-1059	1
CABLE-THROTTLE (Ref # 54012A)	54012-1110	1
CABLE,TACHOMETER (Ref # 54018)	54018-015	1
CLAMP,CABLE (Ref # 92037)	92037-093	1
CLAMP,THROTTLE CABLE (Ref # 92037A)	92037-1189	1
CLAMP,CLUTCH CABLE (Ref # 92037C)	92037-1253	1
BOLT-UPSET 6X14 (Ref # 110)	112B0614	1
WASHER PLAIN 6MM (Ref # 411)	411B0600	1
WASHER SPRING 6MM (Ref # 461)	461F0600	1