


## 1998 1100 STX PARTS DIAGRAM

Carburetor Parts

E1612



## 1998 1100 STX PARTS LIST

### Carburetor Parts

ITEM NAME	PART NUMBER	QUANTITY
GASKET,DIAPHRAGM COVER (Ref # 11060)	11060-3789	1
GUIDE,VACUUM VALVE (Ref # 13070)	13070-3726	1
COVER-COMP,MIXING (Ref # 14041)	14041-1100	1
COVER,DIAPHRAGM (Ref # 14090)	14090-3816	1
JET-NEEDLE,N6PA (Ref # 16017)	16017-3702	1
VALVE-FLOAT (Ref # 16030)	16030-3704	1
ARM-FLOAT (Ref # 16055)	16055-3702	1
VALVE-CHECK (Ref # 16087)	16087-3706	1
VALVE,VACUUM (Ref # 16126)	16126-3705	1
JET-SLOW,#35 (Ref # 16158)	16158-3720	1
JET-SLOW,#32 (Ref # 16158A)	16158-3723	1
CASE,JET (Ref # 32099)	32099-3833	1
DIAPHRAGM,CARBURETOR (Ref # 43028)	43028-3711	1
DIAPHRAGM (Ref # 43028A)	43028-3713	1
PACKING,JET CASE (Ref # 43049)	43049-3713	1
CASE-PUMP (Ref # 59336)	59336-3715	1
SCREW (Ref # 92009)	92009-1771	1
SCREW,3X8 (Ref # 92009A)	92009-3712	1
SCREW,4X8 (Ref # 92009B)	92009-3804	1
SCREW,VALVE GUIDE (Ref # 92009C)	92009-3839	1
SCREW,DIAPHRAGM COVER (Ref # 92009D)	92009-3840	1
SCREW,MIXING COVER (Ref # 92009E)	92009-3841	1
RING-O,VACUUM VALVE GUIDE (Ref # 92055)	92055-3749	1
JET-MAIN,#165 (Ref # 92063)	92063-3720	1
JET-MAIN,#160 (Ref # 92063A)	92063-3722	1
SPRING,VACUUM VALVE (Ref # 92144)	92144-1962	1
SPRING,FLOAT ARM (Ref # 92144A)	92144-3764	1
SPRING,JET NEEDLE (Ref # 92145)	92145-3707	1
COLLAR,JET NEEDLE (Ref # 92152)	92152-3706	1