


# 1970 Mach III PARTS DIAGRAM

METERS (H1/A/C)



**(H1/A**

# 1970 Mach III PARTS LIST

METERS (H1/A/C)

| ITEM NAME                        | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| SPEEDOMETER ASSY MPH (Ref # 1)   | 25005-027   | 1        |
| TACHOMETER ASSY (Ref # 2)        | 25015-006   | 1        |
| SOCKET SPEEDOMETER (Ref # 3)     | 25011-003   | 1        |
| SOCKET TACHOMETER (Ref # 4)      | 25011-011   | 1        |
| BULB 12V 3W (Ref # 5)            | 92069-018   | 4        |
| BRACKET SPEEDOMETER (Ref # 6)    | 25008-009   | 1        |
| CLAMP CABLE (Ref # 7)            | 25022-002   | 2        |
| DAMPER RUBB SPEEDMETR (Ref # 8)  | 92075-034   | 4        |
| DAMPER RUBB SPEEDMETR (Ref # 9)  | 92075-035   | 2        |
| WASHER PL 5.5X20X1.2 (Ref # 10)  | 92022-104   | 4        |
| WASHER PLAIN 8MM (Ref # 11)      | 411B0800    | 6        |
| WASHER SPRING 5MM (Ref # 12)     | 461F0500    | 4        |
| NUT,5MM (Ref # 13)               | 311B0500    | 4        |
| DAMPER RUBB SPEEDMETR (Ref # 14) | 92075-024   | 2        |
| WASHER 6.5X20X1.6T (Ref # 15)    | 92022-125   | 2        |
| WASHER SPRING 6MM (Ref # 16)     | 461F0600    | 2        |
| NUT 6MM (Ref # 17)               | 311B0600    | 2        |
| COVER-SPEEDOMETER (Ref # 18)     | 25012-003   | 2        |