


1999 1100 STX PARTS DIAGRAM

Meters



1999 1100 STX PARTS LIST

Meters

ITEM NAME	PART NUMBER	QUANTITY
WASHER-PLAIN,6MM (Ref # 411)	411S0600	1
BRACKET,HORN (Ref # 11051)	11051-3728	1
SHAFT (Ref # 13107)	13107-3754	1
SENSOR,SPEEDOMETER (Ref # 21176)	21176-3713	1
BRACKET-METER (Ref # 25008)	25008-3709	1
HORN (Ref # 27003)	27003-3704	1
SWITCH,FUEL LEVEL (Ref # 27010)	27010-3742	1
SWITCH,OIL LEVEL (Ref # 27010A)	27010-3753	1
WHEEL-ASSY,PADDLE (Ref # 41073)	41073-3701	1
CLAMP (Ref # 92037)	92037-1173	1
CLAMP (Ref # 92037A)	92037-3009	1
BAND (Ref # 92072)	92072-3778	1
DAMPER (Ref # 92075)	92075-1446	1
BOLT,SOCKET,6X10 (Ref # 92151)	92151-3704	1
BOLT,5X10 (Ref # 92151A)	92151-3707	1
DAMPER,METER (Ref # 92160)	92160-3881	1
CLAMP (Ref # 92170)	92170-3718	1
CLAMP (Ref # 92170A)	92170-3734	1
WASHER,5.9X16X1.5 (Ref # 92200)	92200-3714	1
METER-ASSY (Ref # 25031B)	25031-3710	1
METER-ASSY (Ref # 25031C)	25031-3711	1