


1981 KD80

PARTS DIAGRAM

CABLES



1981 KD80

PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
BOLT-UPSET,6X12 (Ref # 1)	112G0612	
WASHER SPRING 6MM (Ref # 2)	461F0600	
WASHER PLAIN 6MM (Ref # 3)	411B0600	
CLAMP,CABLE (Ref # 4)	92037-117	
CABLE,FRONT BRAKE (Ref # 5)	54005-1021	
JOINT-BRAKE ROD (Ref # 6)	92043-082	
NUT-BRAKE ROD ADJUST (Ref # 7)	92015-052	
CABLE, CLUTCH (Ref # 8)	54011-073	
CABLE,THROTTLE (Ref # 9)	54012-1056	
WIRING HARNESS,EXTNSN (Ref # 10)	26011-006	
BAND,SHORT (Ref # 11)	92072-030	
BAND,MIDDLE (Ref # 12)	92072-031	
BAND,LONG (Ref # 13)	92072-032	
BAND,WIRING HARNESS (Ref # 14)	92072-056	
BOLT-UPSET,6X12 (Ref # 15)	112G0612	
WASHER SPRING 6MM (Ref # 16)	461F0600	
WASHER PLAIN 6MM (Ref # 17)	411B0600	
CLAMP-CABLE (Ref # 18)	92037-046	