


1982 KE100

PARTS DIAGRAM

CABLES



1982 KE100

PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
DUST COVER-BRKE CABLE (Ref # 49016)	54009-008	1
CABLE,SPEEDOMETER (Ref # 54001)	54001-032	1
CABLE-BRAKE (Ref # 54005)	54005-1035	1
CABLE,CLUTCH (Ref # 54011A)	54011-075	1
CABLE-THROTTLE (Ref # 54012)	54012-1104	1
SCREW-PAN-WS-CROS (Ref # 92009)	223B0510	1
NUT-BRAKE ROD ADJUST (Ref # 92015)	92015-052	1
CLAMP-CABLE (Ref # 92037)	92037-069	1
CLAMP-CABLE (Ref # 92037A)	92037-046	1
JOINT-BRAKE ROD (Ref # 92043)	92043-082	1
SPRING,COIL (Ref # 92081)	54025-004	1
BOLT 6X12 (WP) (Ref # 186)	186B0612	1