


2007 Ultra 250X PARTS DIAGRAM

Super Charger

E1460



2007 Ultra 250X PARTS LIST

Super Charger

ITEM NAME	PART NUMBER	QUANTITY
BOLT-FLANGED,10X14 (Ref # 130)	130CD1014	1
BOLT-FLANGED,10X30 (Ref # 130A)	130CD1030	4
BOLT-FLANGED,10X40 (Ref # 130B)	130CD1040	2
BOLT-FLANGED-SMALL,6X18 (Ref # 132)	132BD0618	16
GASKET,SUPERCHARGER (Ref # 11061)	11061-3745	2
SHAFT (Ref # 13107)	13107-3791	1
PLATE,BELT TENSIONER (Ref # 13271)	13271-3922	1
COVER,BELT (Ref # 14091)	14091-3811	1
COMPRESSOR-AIR,SUPERCHARGER (Ref # 15051)	15051-3701	1
PIPE-INTAKE,S/C IN (Ref # 16060)	16060-3721	1
PIPE-INTAKE,S/C OUT (Ref # 16060A)	16060-3722	1
PACKING (Ref # 43049)	43049-3718	2
PULLEY-BELT (Ref # 49079)	49079-3701	1
PULLEY-BELT (Ref # 49079A)	49079-3702	1
GAUGE,OIL (Ref # 52005)	52005-3711	1
BELT,6PK755 (Ref # 59011)	59011-3701	1
WASHER,32X10.5X4 (Ref # 92022)	92022-3023	1
RING-SNAP,47MM (Ref # 92033)	92033-3734	1
RING-SNAP (Ref # 92033A)	92033-3736	1
BEARING-BALL,17X47X14 (Ref # 92045)	92045-3742	1
BOLT,6X18 (Ref # 92150)	92150-3729	2
COLLAR,17X30X9.5 (Ref # 92152)	92152-3747	1
BOLT,DRAIN (Ref # 92153)	92153-3749	1
BOLT,FLANGED,10X130 (Ref # 92153A)	92153-3753	1
BOLT,6X18 (Ref # 92154)	92154-3701	1
BOLT,6X10 (Ref # 92154A)	92154-3702	5
WASHER,6.5X16X2.0 (Ref # 92200)	92200-1543	2
WASHER,10.5X26X4 (Ref # 92200A)	92200-3798	2
WASHER (Ref # 92200B)	92200-3801	1

2007 Ultra 250X PARTS LIST

Super Charger

ITEM NAME	PART NUMBER	QUANTITY
WASHER-PLAIN,10MM (Ref # 411)	411S1000	4