


2016 W800 (European)

PARTS DIAGRAM

Swingarm

F2141



2016 W800 (European)

PARTS LIST

Swingarm

ITEM NAME	PART NUMBER	QUANTITY
NUT-HEX-SMALL,8MM (Ref # 317)	317BA0800	2
BEARING-BALL,#6203 (Ref # 601)	601A6203	1
ARM-COMP-SWING (Ref # 33001)	33001-0566	1
SHAFT-SWING ARM (Ref # 33032)	33032-1192	1
ADJUSTER-CHAIN (Ref # 33040)	33040-0076	2
SLEEVE,SWING ARM,L=186.6 (Ref # 42036)	42036-1352	1
GUARD,CHAIN (Ref # 55020)	55020-1686	1
SCREW,6X18 (Ref # 92009)	92009-1663	1
NUT,POP,6MM,L=15 (Ref # 92015)	92015-1791	1
COLLAR,L=4.5 (Ref # 92027)	92027-1965	1
RING-SNAP,40MM (Ref # 92033)	92033-1040	1
BEARING-NEEDLE,BHTM2530-1 (Ref # 92046)	92046-1035	2
SEAL-OIL (Ref # 92049)	92049-1047	1
SEAL-OIL,MH25334 (Ref # 92049A)	92049-1060	1
COLLAR,RR AXLE,L=14 (Ref # 92143)	92143-1188	1
BOLT,8X55 (Ref # 92153)	92153-1407	2
NUT,PIVOT,16MM (Ref # 92210)	92210-1077	1