


## 1988 KDX80 PARTS DIAGRAM

Swingarm

F2141-0001



# 1988 KDX80 PARTS LIST

## Swingarm

| ITEM NAME                                  | PART NUMBER   | QUANTITY |
|--------------------------------------------|---------------|----------|
| CAP (Ref # 11012)                          | 11012-1263    | 4        |
| GUIDE-CHAIN,FR (Ref # 12053)               | 12053-1074    | 1        |
| ARM-COMP-SWING,SILVER NO.15 (Ref # 33001B) | 33001-1308-X3 | 1        |
| SHAFT-SWING ARM,PIVOT (Ref # 33032)        | 33032-1031    | 1        |
| ADJUSTER-CHAIN (Ref # 33040)               | 33040-1055    | 2        |
| SLEEVE,SWING ARM,L=34 (Ref # 42036)        | 42036-1067    | 2        |
| GUARD,CHAIN,RR (Ref # 55020)               | 55020-1163    | 1        |
| BOLT,6X39 (Ref # 92001)                    | 92001-1463    | 2        |
| SCREW,6X10,WHITE (Ref # 92009)             | 92009-1286    | 2        |
| NUT,LOCK,12MM (Ref # 92015)                | 92015-1063    | 1        |
| NUT,LOCK,6MM (Ref # 92015A)                | 92017-014     | 1        |
| COLLAR (Ref # 92027)                       | 92027-1183    | 2        |
| COLLAR,CHAIN GUIDE (Ref # 92027A)          | 92027-1495    | 1        |
| BEARING-NEEDLE (Ref # 92046)               | 92046-1046    | 2        |
| RING-O,SWING ARM (Ref # 92055)             | 92055-1240    | 4        |
| ROLLER,CHAIN GUIDE (Ref # 92122)           | 92122-1030    | 1        |
| BOLT-FLANGED,6X45 (Ref # 130)              | 130G0645      | 2        |
| BOLT-FLANGED,6X50 (Ref # 130A)             | 130G0650      | 1        |
| NUT-HEX,6MM (Ref # 311)                    | 311B0600      | 2        |
| WASHER-PLAIN,6MM (Ref # 411)               | 411B0600      | 1        |