


# 2000 Super Sherpa

## PARTS DIAGRAM

### Turn Signals



# 2000 Super Sherpa

## PARTS LIST

### Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
GASKET,TURN SIGNAL LAMP LENS (Ref # 11009)	11009-1128	4
CAP,SIGNAL LAMP (Ref # 11012)	11012-1367	4
LAMP-ASSY-SIGNAL,FR (Ref # 23037)	23037-1201	2
LAMP-ASSY-SIGNAL,RR (Ref # 23037A)	23037-1371	2
LENS-SIGNAL LAMP (Ref # 23048)	23048-1076	4
BRACKET-SIGNAL LAMP,RR (Ref # 23051)	23051-1246	2
WASHER,PLAIN,4MM (Ref # 23058)	23058-002	8
SCREW,TAPPING,4X30 (Ref # 92009)	92009-1056	8
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	4
BULB,12V 32CP(23W) (Ref # 92069)	92069-055	4
BOLT,FLANGED,6X16 (Ref # 92150)	92150-1506	2