


# 2002 KLX110 PARTS DIAGRAM

Swingarm

F2141



## 2002 KLX110 PARTS LIST

### Swingarm

ITEM NAME	PART NUMBER	QUANTITY
GUIDE-CHAIN,FR (Ref # 12053)	12053-1459	1
GUIDE-CHAIN,RR (Ref # 12053A)	12053-1460	1
ARM-COMP-SWING,SILVER (Ref # 33001)	33001-1622-CE	1
SHAFT-SWING ARM (Ref # 33032A)	33032-1203	1
ADJUSTER-CHAIN (Ref # 33040)	33040-1006	2
NUT,6MM (Ref # 92015)	92015-1391	4
WASHER,6.5X16X2 (Ref # 92022)	92022-1565	2
BUSHING-RUBBER (Ref # 92092)	92092-005	2
BOLT,6X20 (Ref # 92150)	92150-1339	3
NUT,LOCK,12MM (Ref # 92210)	92210-1373	1