


2014 Z1000 ABS

PARTS DIAGRAM

Turn Signals



2014 Z1000 ABS

PARTS LIST

Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-WP-CROS,4X8 (Ref # 224)	224AB0408	4
LAMP-ASSY-SIGNAL,RR,LH (Ref # 23037)	23037-0260	1
LAMP-ASSY-SIGNAL,RR,RH (Ref # 23037A)	23037-0261	1
LAMP-ASSY-SIGNAL,FR,LH (Ref # 23037B)	23037-0262	1
LAMP-ASSY-SIGNAL,FR,RH (Ref # 23037C)	23037-0263	1
LENS-SIGNAL LAMP (Ref # 23048)	23048-0023	2
LENS-SIGNAL LAMP (Ref # 23048A)	23048-0024	2
BULB,12V 10W (Ref # 92069)	92069-0076	4
SCREW,2.9X22 (Ref # 92172)	92172-0395	4
WASHER,NUT 4MM (Ref # 92200)	92200-0854	4
WASHER (Ref # 92200A)	92200-0855	4