


1999 KX100 PARTS DIAGRAM

Labels(KX100-C2)

F2860A



1999 KX100 PARTS LIST

Labels(KX100-C2)

ITEM NAME	PART NUMBER	QUANTITY
MARK,SWING ARM,100 (Ref # 56051)	56051-1876	2
PATTERN,FUEL TANK,LH (Ref # 56062)	56062-1564	1
PATTERN,FUEL TANK,RH (Ref # 56062A)	56062-1565	1
PATTERN,SHROUD,RH (Ref # 56062B)	56062-1566	1
LABEL-WARNING,NOISE (Ref # 56040)	56040-1101	1
LABEL-WARNING,GASOLINE/OIL (Ref # 56040A)	56040-1129	1
LABEL-WARNING,GASOLINE/OIL (Ref # 56040B)	56040-1306	1
LABEL-WARNING,WARRANTY (Ref # 56040C)	56040-1335	1