


## 2002 KX100 PARTS DIAGRAM

Shock Absorber(s)

F2280



## 2002 KX100 PARTS LIST

Shock Absorber(s)

| ITEM NAME                                     | PART NUMBER   | QUANTITY |
|---|---------------|----------|
| CAP,VALVE AIR (Ref # 11012)                   | 11012-1391    | 1        |
| GUIDE,SPRING (Ref # 13070)                    | 13070-1233    | 1        |
| RESERVOIR,SHOCKABSORBER (Ref # 43078)         | 43078-1112    | 1        |
| CYLINDER-SHOCKABSORBER (Ref # 43089)          | 43089-1162    | 1        |
| SHOCKABSORBER,I.SILVER (Ref # 45014)          | 45014-1662-8V | 1        |
| ROD,SHOCKABSORBER (Ref # 46102)               | 46102-1411    | 1        |
| BOLT,DRAIN (Ref # 92002)                      | 92002-1955    | 1        |
| NUT,SPRING ADJUST (Ref # 92015)               | 92015-1679    | 1        |
| NUT,SPRING ADJUST LOCK (Ref # 92015A)         | 92015-1713    | 1        |
| RING-SNAP,REARSHOCK (Ref # 92033)             | 92033-1091    | 1        |
| RING-SNAP,SHOCKABSORBER (Ref # 92033A)        | 92033-1211    | 1        |
| RING-O,ROD (Ref # 92055)                      | 92055-1334    | 1        |
| RING-O (Ref # 92055A)                         | 92055-1383    | 1        |
| SPRING,SHOCKABSORBER,K=4.6,SIL (Ref # 92144)  | 92144-1570-8V | 1        |
| SPRING,SHOCKABSORBER,K=5.0,SIL (Ref # 92144A) | 92144-1571-8V | 1        |
| SPRING,SHOCKABSORBER,K=4.8,SIL (Ref # 92144B) | 92144-1945-8V | 1        |
| SPRING,SHOCKABSORBER,K=4.4,SIL (Ref # 92145)  | 92145-1371-8V | 1        |