


## 2001 KX500 PARTS DIAGRAM

Generator

E1810



## 2001 KX500 PARTS LIST

Generator

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-WP-CROS (Ref # 235)	235B0616	1
STATOR (Ref # 21003)	21003-1307	1
ROTOR,MAGNETO (Ref # 21007)	21007-1241	1
IGNITER (Ref # 21119)	21119-1267	1
NUT,FLANGED,12MM (Ref # 92015)	92015-1156	1
KEY,WOODRUFF (Ref # 92038)	92038-001	1