


2003 KX500 PARTS DIAGRAM

Shock Absorber(s)

F2280



2003 KX500 PARTS LIST

Shock Absorber(s)

ITEM NAME	PART NUMBER	QUANTITY
CAP,AIR VALVE (Ref # 11012)	11012-1552	1
GUIDE,SPRING (Ref # 13070)	13070-1161	1
GUIDE,SPRING (Ref # 13070A)	13070-1165	1
PISTON,SHOCKABSORBER (Ref # 13256)	13256-1057	1
RESERVOIR,SHOCKABSORBER (Ref # 43078)	43078-1094	1
CYLINDER-SHOCKABSORBER (Ref # 43089)	43089-1160	1
SHOCKABSORBER,I.SILVER (Ref # 45014)	45014-1652-8V	1
ROD,SHOCKABSORBER (Ref # 46102)	46102-1405	1
BOLT,DRAIN (Ref # 92002)	92002-1955	1
NUT,SPRING ADJUST (Ref # 92015)	92015-1703	1
NUT,SPRING ADJUST LOCK (Ref # 92015A)	92015-1704	1
RING-SNAP (Ref # 92033)	92033-1209	1
SEAL-OIL (Ref # 92049)	92049-1407	1
RING-O,ROD (Ref # 92055)	92055-1346	1
RING-O (Ref # 92055A)	92055-1383	1
SPRING,SHOCKABSORBER,K=5.3,SIL (Ref # 92144)	92144-1505-8V	1
SPRING,SHOCKABSORBER,K=5.5,SIL (Ref # 92144A)	92144-1506-8V	1
SPRING,SHOCKABSORBER,K=5.7,SIL (Ref # 92144B)	92144-1929-8V	1