

Drive Shaft-Front

Figure 1 is a perspective view of a bracket assembly 92173. The assembly includes a bracket 92173 with a vertical section 92192 and a horizontal section 92191. Two screws 92173A are shown securing the bracket to a surface.



2025 Mule PRO-MX PARTS LIST

Drive Shaft-Front

ITEM NAME	PART NUMBER	QUANTITY
GASKET (Ref # 11061)	11061-Y067	1
GEAR-ASSY,FR (Ref # 13101)	13101-Y004	1
COVER-ASSY (Ref # 16146)	16146-Y002	1
ACTUATOR (Ref # 16172)	16172-0030	1
BEARING-NEEDLE,16X20X16.8 (Ref # 92046)	92046-0630	1
SEAL-OIL (Ref # 92049)	92049-0749	2
RING-O (Ref # 92055)	92055-Y070	1
RING-O (Ref # 92055A)	92055-Y071	1
RING-O (Ref # 92055B)	92055-Y073	1
PLUG (Ref # 92066)	92066-Y022	1
BOLT,FLANGE,10X14 (Ref # 92154)	92154-Y219	1
BOLT,FLANGE,6X18 (Ref # 92154A)	92154-Y222	4
BOLT,FLANGE,6X20 (Ref # 92154B)	92154-Y223	3
CLAMP,10.5 (Ref # 92173)	92173-Y023	1
CLAMP (Ref # 92173A)	92173-Y078	2
TUBE,DIFF CASE (Ref # 92192)	92192-Y071	1