


## 1997 GPZ 1100 PARTS DIAGRAM

Transmission

E1361



## 1997 GPZ 1100 PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
CIRCLIP-TYPE-C,28MM (Ref # 480)	480J2800	1
CIRCLIP (Ref # 480A)	480J2900	1
BALL-STEEL,5/32" (Ref # 600)	600A0500	1
SHAFT-TRANSMISSION INPUT,15T (Ref # 13127)	13127-1196	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-1205	1
GEAR,OUTPUT LOW,42T (Ref # 13129)	13129-1534	1
SPROCKET-OUTPUT,17T (Ref # 13144)	13144-1239	1
GEAR,OUTPUT 4TH,32T (Ref # 13260)	13260-1139	1
GEAR,INPUT 2ND,18T (Ref # 13260A)	13260-1468	1
GEAR,OUTPUT 2ND,37T (Ref # 13260B)	13260-1469	1
GEAR,INPUT 3RD&4TH,22T&24T (Ref # 13260C)	13260-1470	1
GEAR,OUTPUT 3RD,35T (Ref # 13260D)	13260-1471	1
GEAR,INPUT 5TH,26T (Ref # 13260E)	13260-1499	1
GEAR,INPUT TOP,28T (Ref # 13260F)	13260-1500	1
GEAR,OUTPUT 5TH,30T (Ref # 13260G)	13260-1501	1
GEAR,OUTPUT TOP,29T (Ref # 13260H)	13260-1502	1
NUT,20MM (Ref # 92015)	92015-1210	1
WASHER,TOOTHED,28X40X1.8 (Ref # 92022)	92022-1728	1
WASHER,22.3X35X1.6 (Ref # 92022A)	92022-212	1
WASHER,TOOTHED,26X35.5X1.5 (Ref # 92024)	92024-042	1
WASHER,TOOTHED,30.5X38X1 (Ref # 92024A)	92024-069	1
BUSHING, TOP GEAR (Ref # 92028)	92028-1124	1
BUSHING,OUTPUT 3RD&4TH (Ref # 92028A)	92028-1363	1
RING-SNAP,20X25.5X1.2 (Ref # 92033)	92033-025	1
BEARING-BALL (Ref # 92045)	92045-1186	1
BEARING-NEEDLE,FWF-223014 (Ref # 92046)	92046-031	1
RACE,INPUT SHAFT (Ref # 92048)	92048-1052	1
RACE,30X38X15 (Ref # 92048A)	92048-1053	1
COLLAR,28X40X33.5 (Ref # 92143)	92143-1731	1

## 1997 GPZ 1100 PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
WASHER,TOOTHED,23.9X45X1.0 (Ref # 92200)	92200-1234	1