


1993 KDX200

PARTS DIAGRAM

Meter

F2530



1993 KDX200

PARTS LIST

Meter

ITEM NAME	PART NUMBER	QUANTITY
NUT-HEX (Ref # 311)	311B0500	2
BRACKET-METER (Ref # 25008)	25008-1159	1
WASHER,5.2X16X1.2 (Ref # 92022)	92022-263	2
COLLAR,METER BRACKET (Ref # 92027)	92027-1585	4
DAMPER (Ref # 92075)	92075-013	2
BOLT,6X14 (Ref # 92150)	92150-1340	2
DAMPER (Ref # 92160)	92160-1110	2
SPEEDOMETER,TRIP(MILE) (Ref # 25005)	25005-1496	1
SPEEDOMETER,TRIP(KM) (Ref # 25005A)	25005-1497	1