

1981 LTD Belt

PARTS DIAGRAM

CHASSIS ELECTRICAL EQUIPMENT ('81-'83 D2

NO IMAGE AVAILABLE

1981 LTD Belt

PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT ('81-'83 D2

ITEM NAME	PART NUMBER	QUANTITY
HARNESS,MAIN (Ref # 26001)	26001-1217	1
WIRING HARNESS,TL LMP (Ref # 26001C)	26002-046	1
FUSE ASSY (Ref # 26004)	26004-035	1
FUSE-ASSY,ACCESSORY (Ref # 26004A)	26004-1014	1
FUSE 10A (Ref # 26006)	26006-003	3
FUSE-20A (Ref # 26006A)	26006-005	2
FUSE,10A,L=30M/M (Ref # 26006B)	26006-1002	3
LEAD WIRE,SIGNAL LAMP (Ref # 26011)	26011-063	1
WIRE,LEAD (Ref # 26011A)	26011-095	2
WIRE LEAD,BATTERY GRD (Ref # 26011B)	26011-1022	1
FB BAT FB12A-A (Ref # 26012B)	26012-1004	1
RELAY-TURN SIGNAL (Ref # 27002)	27002-011	1
HORN (Ref # 27003)	27003-1019	1
SWITCH,TURN SIGNAL OP (Ref # 27010)	27010-1016	1
SWITCH,BK LIGHT IND (Ref # 27010B)	28019-002	1
BAND,SHORT (Ref # 92072)	92072-030	4
BAND,MIDDLE (Ref # 92072A)	92072-031	7
BAND,LONG (Ref # 92072B)	92072-032	3
BAND,WIRING HARNESS (Ref # 92072C)	92072-056	1
BAND,BREATHER WIRE (Ref # 92072D)	92072-067	2
DAMPER RUBBER,FUSE (Ref # 92075)	92075-279	1
BOLT-SMALL-UPSET,8X16 (Ref # 114)	115G0816	2
SCREW PAN HEAD 6X20 (Ref # 220)	220B0620	2
WASHER PLAIN 6MM (Ref # 410)	410B0600	2
WASHER SPRING 6MM (Ref # 461)	461F0600	2
WASHER SPRING 8MM (Ref # 461A)	461F0800	2