


1984 GPz 750

PARTS DIAGRAM

TRANSMISSION

E1361-0117



1984 GPz 750

PARTS LIST TRANSMISSION

| ITEM NAME | PART NUMBER | QUANTITY |
|--------------------------------------|-------------|----------|
| SHAFT,DRIVE (Ref # 13127) | 13127-1018 | 1 |
| SHAFT-TRANSMISSION OU (Ref # 13128) | 13128-1051 | 1 |
| LOW GEAR,OUTPUT SHAFT (Ref # 13129) | 13129-1046 | 1 |
| 2ND GEAR,OUTPUT SHAFT (Ref # 13129A) | 13129-1047 | 1 |
| 3RD GEAR,OUTPUT SHAFT (Ref # 13129B) | 13129-1048 | 1 |
| 4TH GEAR,OUTPUT SHAFT (Ref # 13129C) | 13129-1049 | 1 |
| TOP GEAR,DRIVEN SHAFT (Ref # 13129D) | 13129-1201 | 1 |
| GEAR,INPUT TOP,24T (Ref # 13129E) | 13129-1425 | 1 |
| GEAR,INPUT 3RD&22T (Ref # 13129F) | 13260-1202 | 1 |
| GEAR,INPUT 4TH,25T (Ref # 13129G) | 13129-1446 | 1 |
| 2ND GEAR,DRIVE (Ref # 13129H) | 13130-041 | 1 |
| SPROCKET-OUTPUT,15T (Ref # 13144) | 13144-1084 | 1 |
| NUT,20MM (Ref # 92015) | 92015-1254 | 1 |
| WASHER,PLAIN (Ref # 92022) | 92022-1026 | AR |
| WASHER (Ref # 92022A) | 92200-1065 | 1 |
| WASHER THRUST (Ref # 92022B) | 92022-112 | 2 |
| SHIM-KICK SHAFT (Ref # 92022C) | 92022-144 | AR |
| WASHER PLAIN (Ref # 92022D) | 92022-161 | 2 |
| WASHER,LOCK (Ref # 92022E) | 92024-069 | 3 |
| COLLAR,25X32X23.5L (Ref # 92027) | 92027-1106 | 1 |
| BUSHING,DRV SHFT TOP (Ref # 92028) | 92028-1007 | 1 |
| BUSHING,27X34X18.6 (Ref # 92028A) | 92028-1151 | 1 |
| BUSHING,INPUT SHAFT (Ref # 92028B) | 92028-1199 | 1 |
| CIRCLIP (Ref # 92033) | 92033-015 | 2 |
| CIRCLIP (Ref # 92033A) | 92033-026 | 2 |
| BEARING,BALL (Ref # 92045) | 92045-035 | 2 |
| BEARING-NEEDLE,20V271 (Ref # 92046) | 92046-1045 | 2 |
| CIRCLIP,30MM (Ref # 480) | 480J3000 | 3 |
| BALL STEEL 5/32' (Ref # 600) | 600A0500 | 3 |