


1984 KZ700-A1

PARTS DIAGRAM

CABLES

F25-40-01:17



1984 KZ700-A1

PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 54001)	54001-1012	1
CABLE-CLUTCH (Ref # 54011)	54011-1101	1
CABLE-THROTTLE (Ref # 54012)	54012-1117	1
CLAMP,CABLE (Ref # 92037)	92037-093	2
CLAMP,CABLE (Ref # 92037A)	92037-1602	1
SCREW-PAN-CROS (Ref # 220)	220C0510	1