

PARTS DIAGRAM

SWING ARM

Let the Good Times Roll®



1986 Ninja® 1000R

PARTS LIST

SWING ARM

ITEM NAME	PART NUMBER	QUANTITY
GUIDE-CHAIN (Ref # 12053)	12053-1186	1
ARM-COMP-SWING,SILVER (Ref # 33001)	33001-1240-X3	1
SHAFT-SWING ARM (Ref # 33032)	33032-1115	1
SLEEVE,REAR AXLE,LH (Ref # 42036)	42036-1153	1
SLEEVE,REAR AXLE,RH (Ref # 42036A)	42036-1154	1
SLEEVE,16.1X25X254 (Ref # 42036B)	42036-1155	1
BOLT (Ref # 92002)	92002-1452	2
SCREW,6X10 (Ref # 92009)	92009-1286	2
NUT,16M/M (Ref # 92015)	92015-1041	1
CLAMP (Ref # 92037)	92037-1565	1
BEARING-NEEDLE (Ref # 92046)	92046-1035	2
SEAL-OIL (Ref # 92049)	92049-1166	2
BOLT-UPSET-WSP (Ref # 187)	187D0610	1
W-PLAIN-S (Ref # 410)	410E1000	2