


1987 KX500

PARTS DIAGRAM

TRANSMISSION

E1361-0183



1987 KX500

PARTS LIST TRANSMISSION

ITEM NAME	PART NUMBER	QUANTITY
SHAFT-TRANSMISSION IN (Ref # 13127)	13127-1143	1
SHAFT-TRANSMISSION OU (Ref # 13128)	13128-1142	1
TOP GEAR,OUTPUT,19T (Ref # 13129)	13129-1133	1
LOW GEAR,OUTPUT,32T (Ref # 13129A)	13129-1180	1
GEAR,INPUT 2ND,20T (Ref # 13129B)	13129-1741	1
GEAR,INPUT 3RD,22T (Ref # 13129C)	13129-1742	1
GEAR.INPUT 4TH,22T (Ref # 13129D)	13129-1743	1
GEAR,INPUT TOP,24T (Ref # 13129E)	13129-1744	1
GEAR,OUTPUT 2ND,29T (Ref # 13129F)	13129-1746	1
GEAR,OUTPUT 3RD,26T (Ref # 13129G)	13129-1747	1
GEAR,OUTPUT 4TH,21T (Ref # 13129H)	13129-1748	1
ENGINE SPROCKET,15T (Ref # 13144)	13144-069	1
ENGINE SPROCKET,14T (Ref # 13144A)	13144-1005	1
ENGINE SPROCKET,13T (Ref # 13144B)	13144-1027	1
NUT BEARING ADJUST (Ref # 92015)	42045-008	1
WASHER-PLAIN 25MM (Ref # 92022)	92022-159	2
WASHER,17.3X28X1.0 (Ref # 92022A)	92022-255	1
WASHER-LOCK (Ref # 92022B)	92024-038	4
WASHER,LOCK (Ref # 92022C)	92024-065	1
COLLAR,25X32X10.5 (Ref # 92027)	92143-1370	1
CIRCLIP (Ref # 92033)	92033-026	6
CIRCLIP,18MM (Ref # 92033A)	92033-029	1
CIRCLIP,16MM (Ref # 92033B)	92033-032	1
BEARING-NEEDLE,KT2026 (Ref # 92046)	92046-1170	1
BEARING-NEEDLE (Ref # 92046A)	92046-1184	1
"O" RING (Ref # 92055)	92055-035	1