


1975 MC1-B

PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS ('73-'75 MC1/M)



1975 MC1-B

PARTS LIST

SWING ARM/SHOCK ABSORBERS ('73-'75 MC1/M

ITEM NAME	PART NUMBER	QUANTITY
ARM,SWINGING (Ref # 1)	33001-055	
SHAFT,SWING ARM PIVOT (Ref # 2)	33032-043	
WASHER PLAIN 12MM (Ref # 3)	410B1200	
BUSH SWING ARM SHAFT (Ref # 4)	92092-005	
WASHER SPRING 12MM (Ref # 5)	461F1200	
NUT-HEX-FINE (Ref # 6)	314B1200	
ADJUSTER CHAIN (Ref # 7)	33040-008	
NUT 6MM (Ref # 8)	311B0600	
WASHER PLAIN 6MM (Ref # 9)	410B0600	
WASHER SPRING 6MM (Ref # 10)	461F0600	
GUARD,CHAIN (Ref # 11)	55020-012	
BOLT-UPSET 6X14 (Ref # 12)	112B0614	
BOLT-UPSET 6X14 (Ref # 12)	112B0614	
NUT 6MM (Ref # 13)	311B0600	
SHOCK ABSBR RR (Ref # 14)	45014-100	
SHOCK ABSBR RR (Ref # 14)	45014-100	
NUT 12MM (Ref # 15)	92020-014	
WASHER PLAIN 12MM (Ref # 16)	410B1200	
WASHER SPRING 12MM (Ref # 17)	461F1200	
BOLT HEX HEAD 10X28 (Ref # 18)	113N1028	
WASHER SPRING 10MM (Ref # 19)	461F1000	
TORQUE LINK,RR BRAKE (Ref # 20)	43007-037	
BOLT TORQUE LINK FIT (Ref # 21)	92003-017	
BOLT HEX HEAD 10X25 (Ref # 22)	92003-003	
NUT,10MM (Ref # 23)	314B1000	
WASHER SPRING 10MM (Ref # 24)	461F1000	
PIN COTTER 2.0X15 (Ref # 25)	550D2015	