


1973 G3SS-C

PARTS DIAGRAM

METER/HEADLIGHT ('69-'73)



Ref. No. 1

- 1
- 2
- 3
- 4, 28, 31~34
- 6~18
- 6~20
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28
- 29
- 30
- 31
- 32
- 33
- 34
- 35
- 36
- 37
- 38
- 39
- 40

1973 G3SS-C

PARTS LIST

METER/HEADLIGHT ('69-'73)

ITEM NAME	PART NUMBER	QUANTITY
SPEEDOMETER ASSY MPH (Ref # 1)	25001-008	1
BULB 6V 1.5W (Ref # 2)	92069-024	3
SOCKET SPEEDOMETER (Ref # 3)	25011-008	1
LAMP UNIT HEAD (Ref # 6~18)	23004-011	1
LAMP UNIT HEAD (Ref # 6~20)	23003-009	1
UNAVAILABLE IN PRICE BOOK (Ref # 5)	23005-021	1
CASE-HEAD LAMP,BLACK (Ref # 5)	23005-021-21	1
RIM HEAD LAMP (Ref # 6)	23006-020	1
LENS UNIT HEAD LAMP (Ref # 7)	23007-017	1
SEALED BEAM UNIT (Ref # 8)	23007-023	1
BULB 6V 25/25W (Ref # 9)	92069-031	1
SOCKET HEAD LAMP (Ref # 10)	23008-009	1
SOCKET ASSY,HD LIGHT (Ref # 11)	23008-044	1
SPRING LENS FITTING (Ref # 12)	23014-008	1
SCREW ADJUST (Ref # 13)	23019-013	1
WASHER ADJUST (Ref # 14)	23021-007	1
NUT ADJUST (Ref # 15)	23020-012	1
SCREW FITTING (Ref # 16)	23019-014	2
NUT ADJUST (Ref # 17)	23020-013	6
WASHER FITTING (Ref # 18)	23058-001	1
NUT,4MM (Ref # 19)	311B0400	2
WASHER SPRING 4MM (Ref # 20)	461F0400	2
SCREW OVL CNTSNK 5X8 (Ref # 21)	222E0508A	1
GROMMET WIRING HARNES (Ref # 22)	23023-007	2
NUT 10MM (Ref # 23)	92016-027	2
BOLT HEX HEAD 10X20 (Ref # 24)	113N1020	2
WASHER PLAIN 10MM (Ref # 25)	411B1000	2
WASHER SPRING 10MM (Ref # 26)	461F1000	2
WASHER LOCK 10MM (Ref # 27)	463H1000	2

1973 G3SS-C

PARTS LIST

METER/HEADLIGHT ('69-'73)

ITEM NAME	PART NUMBER	QUANTITY
WASHER SPRING 6MM (Ref # 36)	461F0600	3
HORN (Ref # 37)	27003-009	1
HORN (Ref # 38)	27003-055	1
HORN (Ref # 38)	27003-055	1
NUT 6MM (Ref # 39)	311B0600	3