


1979 KZ200-A2

PARTS DIAGRAM

GENERATOR/STARTER MOTOR



1979 KZ200-A2

PARTS LIST

GENERATOR/STARTER MOTOR

ITEM NAME	PART NUMBER	QUANTITY
CLAMP (Ref # 1)	92037-194	
SCREW PAN HEAD 6X14 (Ref # 2)	220B0614	
CLAMP,CABLE (Ref # 3)	92037-1049	
CLAMP,CABLE (Ref # 3)	92037-1049	
STATOR ASSY (Ref # 4)	21003-1002	
SCREW PAN HEAD 6X25 (Ref # 5)	220B0625	
BOLT,10X40 (Ref # 6)	92001-1201	
WOODRUFF KEY (Ref # 7)	92038-001	
ROTOR (Ref # 8)	21007-1010	
ROTOR (Ref # 8)	21007-1010	
ROTOR (Ref # 8)	21007-1010	
SPRING,COIL (Ref # 9)	92081-159	
PIN (Ref # 10)	92043-132	
ROLLER (Ref # 11)	92122-006	
CLUTCH,STARTER (Ref # 12)	13194-008	
BOLT (Ref # 13)	120P0816	
SPROCKET,STARTER CLUT (Ref # 14)	12046-1107	
CHAIN,DYNAMO (Ref # 15)	92057-1009	
STARTER-ELECTRIC (Ref # 16)	21163-1036	
SPROCKET,STARTER MOTO (Ref # 17)	12046-1004	
CIRCLIP,13M/M (Ref # 18)	92033-037	
WASHER,PLAIN,14MM (Ref # 19)	21025-008	
WASHER PLAIN 14MM (Ref # 20)	21025-009	
"O" RING,42.8MM (Ref # 21)	21027-005	
CAP,STARTING MOTOR (Ref # 22)	21017-020	
NUT 6MM (Ref # 23)	312B0600	
WASHER SPRING 6MM (Ref # 24)	461F0600	
WIRE-LEAD,STARTER MOT (Ref # 25)	26011-1201	
"O" RING,62MM (Ref # 26)	21027-006	

1979 KZ200-A2

PARTS LIST

GENERATOR/STARTER MOTOR

ITEM NAME	PART NUMBER	QUANTITY
WASHER,THRUST,1.6T (Ref # 27)	21025-010	
WASHER,THRUST,0.2T (Ref # 28)	21025-011	
BRUSH CARBON (Ref # 29)	21039-004	
SPRING CARBON BRUSH (Ref # 30)	21040-004	
BOLT,FLANGED,6X25 (Ref # 31)	130G0625	
WASHER SPRING 6MM (Ref # 32)	461F0600	
SCREW,PAN HEAD,6X130 (Ref # 33)	92001-1046	