


1974 Mach II

PARTS DIAGRAM

SWING ARM/SHOCK ABSORBERS



1974 Mach II

PARTS LIST

SWING ARM/SHOCK ABSORBERS

ITEM NAME	PART NUMBER	QUANTITY
NUT-LOCK,14MM (Ref # 1)	92019-011	1
CAP,SWING ARM (Ref # 2)	33035-007	2
"O" RING,30MM (Ref # 3)	671B2530	2
SLEEVE-SWING ARM,SHRT (Ref # 4)	33034-013	2
BUSHING-SWING ARM (Ref # 5)	33033-009	2
ARM-COMP-SWING (Ref # 6)	33001-1089	1
ARM-COMP-SWING (Ref # 6)	33001-1089	1
GREASE NIPPLE (Ref # 7)	92005-002	1
NUT SHOCK ABSORBER (Ref # 8)	92020-003	2
WASHER SPRING 10MM (Ref # 9)	461F1000	4
WASHER,PLAIN,10MM (Ref # 10)	92022-246	4
SHOCK ABSBR RR (Ref # 11)	45014-110	2
BUSH SHCK ABS RUBBER (Ref # 12)	45017-001	4
REFLECTOR,REFLEX,REAR (Ref # 13)	28001-030	2
DAMPER RUBBER,REFLEX (Ref # 14)	28016-003	2
SLEEVE-SWING ARM,LONG (Ref # 15)	33034-012	1
SHAFT-SWING ARM PIVOT (Ref # 16)	33032-037	1
BOLT HEX HEAD 10X35 (Ref # 17)	113N1035	2
BUSHING,SHCK ABS RUB (Ref # 18)	45017-018	2
BUSH SHCK ABS PVT SFT (Ref # 19)	45016-003	2
BOLT,FLANGED,8X35 (Ref # 20)	92001-1577	2
BOLT,FLANGED,8X35 (Ref # 20)	92001-1577	AL
WASHER SPRING 8MM (Ref # 21)	461F0800	2
STOPPER,CHAIN ADJUST (Ref # 22)	33044-002	2
ADJUSTER,CHAIN (Ref # 23)	33040-056	2
NUT 8MM (Ref # 24)	312B0800	2
BOLT,8X50 (Ref # 25)	92001-1399	2
BOLT,8X50 (Ref # 25)	92001-1399	2
BOLT (Ref # 26)	92003-096	1