


1978 KZ400-A2

PARTS DIAGRAM

CABLES



1978 KZ400-A2

PARTS LIST

CABLES



ITEM NAME	PART NUMBER	QUANTITY
CABLE, SPEEDOMETER (Ref # 1)	54001-048	
CABLE, CLUTCH (Ref # 2)	54011-069	
CABLE,THROTTLE (Ref # 3)	54012-136	
CABLE,THROTTLE (Ref # 4)	54012-137	
CABLE,THRO.CONT.CLOSE (Ref # 4)	54012-143	
CABLE,TACHOMETER (Ref # 5)	54018-019	
CLAMP,CABLE (Ref # 6)	92037-092	
CLAMP,CABLE (Ref # 7)	92037-090	
CLAMP,CABLE (Ref # 8)	92037-155	